

MPT-II wireless printer – End of Manufacturing Notification

Effective date 2023/01/11

Dear MAICO Customer,

Effective January 11th, 2023, MAICO will no longer offer the MPT-II wireless printer with easyTymp and EROSCAN because the printer reached end of manufacturing status. The new HM-E200 wireless printer is replacing MPT-II wireless printer for easyTymp and EROSCAN in the future.

Technical Support and Repair Service

With the effective date MAICO will not offer repair service for the MPT-II wireless printer. In future, faulty MPT-II wireless printer should be replaced by the new HM-E200 wireless printer.

easyTymp:

- HM-E200 Printer Kit 1161/1171. Item No. 8535090
- easyTymp firmware version must be 1.20.13 or higher

EROSCAN:

- HM-E200 Printer Kit 1161/1171. Item No. 8535090
- EROSCAN firmware version must be 1.13.05 or higher

QUESTIONS:

For further information,
please contact MAICO at +49 30 +0– 7071 46-42 or tcs@maico.biz.
