

Published Date: March 20, 2017

Title: Serial Communication - End of Support

Product(s): GSI-61™

Author: GSI Product Management

Introduction

This bulletin is to announce the end of support for the serial communication interface for the GSI-61. The cable that has been used to support this interface, 8004334, has been discontinued from the manufacturer without a replacement. This is a serial cable with an 8 pin DIN connector at one end and a DB25 connector at the other end.

Options

The upgrade to USB remote board may be an option – check with the service department to confirm if your system can be upgraded and see if the parts for the upgrade are available. You may try and find a similar cable online, but GSI will not be testing other cables for compatibility.

Questions

For further information, please contact Grason-Stadler at (952) 278-4402, (800) 700-2282 or service@grason-stadler.com.

800A-71