

Published Date: **October 08, 2015**

Title: **GSI 37 End of Service**

Product: **GSI 37™**

Author: **GSI Product Management**

End of Service Announcement

This bulletin is to announce the end of service for the GSI 37™. The GSI 37 ended production October, 2008. At that time, we indicated service would be provided for 7 years or to the best of our ability. There are some parts that are no longer available. Going forward we will only be able to service the product based on parts available. Please contact the service department to determine if a part is available.

Questions

For further information, please contact Grason-Stadler at (952) 278-4402, (800) 700-2282 or info@grason-stadler.com.

Thank you for your continued support of GSI.